

**Details**

Manufacturer & Model	<b>TIGUAN Mk2 / 2.0L L4 16V TDI 110kW/148HP DSG DQ38X</b>
KW	<b>110</b>
CV PS	<b>150</b>
Bhp	<b>148</b>
Year	<b>2020</b>
Fuel	<b>Diesel turbo</b>
Regulations	<b>EURO4</b>
New Genius Protocol	<b>FLASH_0928(*)</b>
New Trasdata Plugin	<b>1997, 2008</b>
New Trasdata BENCH	<b>✓</b>
My Genius	<b>✓</b>
Vehicle	<b>Auto</b>
ECU model	<b>BOSCH DQ380, BOSCH DQ381</b>

A New Genius protocol marked with (\*) means that the ECU installed on this vehicle may not support the READ function.

---

## ***DIMSPORT SOLUTIONS FOR THIS VEHICLE***

---



### ***NEW GENIUS***

The stand alone device for the serial communication with the Engine Control Unit (ECU), through the vehicle OBDII socket or via specific diagnostic connectors.



### ***NEW TRASDATA***

A unique tool supporting all microprocessors utilized by any kind of vehicles , for reading and programming operations in BDM, BOOT, JTAG, NBD and BAM mode.



### ***MY GENIUS***

A device for vehicle's owners allowing independent serial reading & programming operations.